Procedures for Programming Boom Functions

		Scanreco MINI/MAXI	
Step	Procedure	Information	**Completed By**
1	Enter Program mode Po 00	Every function in neutral position **Volume Dial at MAX**, release E-stop, push power, Toggle rabbit repeatedly until power light flashes, honk horn	
2	Set Start Speed for Boom Po 02	**** Can Be Done While Operating Boom or By Observing Numbers On display**** Use Power Button To Cycle through to Po 02, Use Joystick for desired function, Set parameter to **30 +/- 5** Via Turtle/Rabbit Toggle ***This number will vary on the display depending on the time or speed trying to be achieved***	
3	Set Maximum Speed for Boom Po 03	*** Can Be Done While Operating Boom or By Observing Numbers On display*** Use Power Button To Cycle through to Po 03, Use Joystick for desired function, Set parameter to **58** via Turtle/Rabbit Toggle ***This number will vary on the display depending on the time or speed trying to be achieved***	
4	Set Turtle Speed Po 04	Use power button to cycle through to Po 04, Set parameter to 68 up to 75 via Turtle/Rabbit Toggle Set slewing to 60 - 64	
5	Save All Programming	Return all Switches to their neutral position, Depress E-stop on Remote Transmitter *** This can be done at any point throughout programming, and is recommended to do after every completed step***	